Blackstone River Coalition Watershed-wide Volunteer Water Quality Monitoring Program Report Card for 2012 Monitoring Season

map									
#	WaterBody	Site Location	Town	Aesthetics	Temp.	DO	% Sat.	Nutrients	
	HEADWATERS TRIBUTARIES								
	Kettle Brook	Stafford Street	Worcester						KEY TO COLOR
	Dark Brook	Auburn High	Auburn						CODES
3	Tatnuck Brook*cwf	VFW-south	Worcester						
4	Tatnuck Brook*cwf	Park Ave.	Worcester						Excellent
5	Leesville Pond	Leesville inflow	Auburn						Good
6	Leesville Pond	Leesville outflow	Worcester						Fair
7	Beaver Brook	Jewish Community Center	Worcester						Poor
	Beaver Brook	Park Ave. Carwash	Worcester						Not Enough Data
	Middle River	St. John's Cemetery	Worcester						
10	Ararat Brook*cwf	Ford Brook	Worcester						Categories
11	Delaney Brook	Delaney Brook	Worcester						(Each category is
12	Broad Meadow Brook	Dunkirk	Worcester						derived from the
13	Broad Meadow Brook	Dupuis	Worcester						combination of the
14	Broad Meadow Brook	Holdridge	Worcester						following factors)
15	Broad Meadow Brook	Knollwood	Millbury						
16	Broad Meadow Brook	Dosco	Millbury						Aesthetics -
17	Cold Spring Brook *cwf	Hatchery Road	Sutton						turbidity, water
18	Quinsigamond River	Outlet Flint Pond	Grafton						appearance, water
19	Quinsigamond River	Rte 140	Grafton						odor & visual
20	Quinsigamond River	Wheeler Road	Grafton						assesments
21	Quinsigamond River	Pleasant Street	Grafton						Temp. - temperature
22	Coal Mine Brook *cwf	Plantation Street	Worcester						DO - dissolved
23	Poor Farm Brook*cwf	Roberto Clemente	Worcester						oxygen
24	Sewall Brook*cwf	School Street**	Boylston						% Sat dissolved
25	Sewall Brook*cwf	Holden Street	Shrewsbury						oxygen % saturation
26	Tilly Brook	Vinny Testa's	Shrewsbury						Nutrients - nitrate &
27	O'Hara Brook	Ideal Terrace	Worcester						orthophospate
28	Bummitt Brook	Pratts Pond	Grafton						
29	Singletary Brook	Sycamore Circle	Millbury						

February 2013

^{*}cwf = designated cold water fishery

^{** =} site experienced no flow conditions during one or more sampling events

Blackstone River Coalition Watershed-wide Volunteer Water Quality Monitoring Program Report Card for 2012 Monitoring Season

map									
#	WaterBody	Site Location	Town	Aesthetics	Temp.	DO	% Sat.	Nutrients	
	BLACKSTONE RIVER							KEY TO COLOR	
30	Blackstone River	outlet of Fisherville Pond @ Rt. 122A	Grafton						CODES
31	Blackstone River	Sutton St. USGS flow station	Northbridge						
32	Blackstone River	Plummer's Landing	Northbridge						Excellent
33	Blackstone River	Tow path north of Stanley Woolen	Uxbridge						Good
34	Blackstone River	Upstream at Gorge off Staples Lane	Blackstone						Fair
35	Blackstone River	Main St. Blackstone/TKO	Blackstone						Poor
36	Blackstone River	River Island Park	Woonsocket						Not Enough Data
37	Blackstone River	Albion Dam	Lincoln						
38	Blackstone River	Slater Mill	Pawtucket						Onto monico
	TRIBUTARIES								Categories
39	Mumford River	Hotel Pond Outlet	Sutton						(Each category is derived from the
40	Mumford River	inlet of L. Manchaug	Sutton						combination of the
41	Mumford River	outlet of L. Manchaug near Parker Rd	Sutton						following factors)
42	Mumford River	Gilboa Street/above WWTP	Douglas						Tollowing factors j
43	Mumford River	Lackey Dam	Uxbridge						Aesthetics -
44	Mumford River	Northbridge Middle School	Uxbridge						turbidity, water
45	Mumford River	downstream @ Depot Street	Uxbridge						appearance, water
46	unnamed tributary	outlet of Whitin Reservoir	Douglas						odor & visual
47	Centerville Brook cw	West Street	Douglas						assesments
48	Cook Allen Brook cwf	upstr of bridge on Johnson Road	Sutton						Temp. - temperature
49	West River ^{*cwr}	Hartford Avenue	Upton						DO - dissolved
50	West River ^{*cwr}	Pleasant and Glen	Upton						oxygen
51	West River ^{*cwr}	Mendon Road	Northbridge						% Sat dissolved
52	West River ^{*cwf}	under Rte. 16 bridge	Uxbridge						oxygen % saturation
53	Miscoe Brook*cwf	Merriam Road	Grafton						Nutrients - nitrate &
54	Warren Brook cwi	Fowler Road Bridge	Upton						orthophospate
55	Center Brook cwf	at Mendon Road	Upton						
56	Meadow Brook cwf	upstream at Blackstone St. bridge	Uxbridge						
57	Emerson Brook ^{*cwr}	Above Quaker Highway	Uxbridge						
58	Bacon Brook*cwr	Balm of Life Springs Road	Uxbridge						

February 2013

^{*}cwf = designated cold water fishery

^{** =} site experienced no flow conditions during one or more sampling events

Blackstone River Coalition Watershed-wide Volunteer Water Quality Monitoring Program Report Card for 2012 Monitoring Season

			I					1			
map											
#	WaterBody	Site Location	Town	Aesthetics	Temp.	DO	% Sat.	Nutrients			
	TRIBUTARIES continued										
59	Mill River	Fitzgerald Street	Hopedale								
60	Mill River	Mill Street	Hopedale								
61	Mill River	Hartford Avenue East	Hopedale								
62	Mill River	Park Street Valati Park	Blackstone								
63	Mill River	Privelege Street	Woonsocket								
64	Clear River ^{*cwr}	RI 102	Burrillville								
65	Chepachet River *cwr	Gazza Road	Burrillville								
66	Tarkiln Brook	Tarkiln Road	Burrillville								
67	Branch River	Rte. 146A/Great Road	N. Smithfield								
68	Cherry Brook	Olo Street	Woonsocket								
69	Crookfall Brook cwr	Sayles Hill Road	Lincoln								
70	Mussey Brook	New River Road	Lincoln								
71	Sneech Brook cwr	Albion Road	Cumberland								
72	Monastery Brook	Mendon Road	Cumberland								
73	Peters River*cwr	Paine Street	Bellingham								
74	Sylvys Brook	Grants Mill Road	Cumberland								
75	Robin Hollow Pond	Dexter Street	Cumberland								
76	Millers River cwr	Hines Road	Cumberland								

KEY TO COLOR CODES

Excellent
Good
Fair
Poor
Not Enough Data

Categories

(Each category is derived from the combination of the following factors)

Aesthetics -

turbidity, water appearance, water odor & visual assesments

Temp. - temperature **DO** - dissolved oxygen

% Sat. - dissolved oxygen % saturation Nutrients - nitrate & orthophospate

February 2013

^{*}cwf = designated cold water fishery

^{** =} site experienced no flow conditions during one or more sampling events