Blackstone River Coalition
Watershed-wide Volunteer Water Quality Monitoring Program
Report Card for 2015 Monitoring Season

map								Nutrient	
#	WaterBody	Site Location	Town	Aesthetics	Temp.	DO	% Sat.	S	
	HEADWATERS TRIBUTARIES								
1	Kettle Brook	Stafford Street	Worcester						KEY TO COLOR
2	Dark Brook	Auburn High	Auburn						CODES
3	Tatnuck Brook ^{com}	VFW-south	Worcester						
4	Tatnuck Brook ^{~cw}	Park Ave.	Worcester						Excellent
5	Leesville Pond	Leesville inflow	Auburn						Good
6	Leesville Pond	Leesville outflow	Worcester						Fair
7	Beaver Brook	Jewish Community	Worcester						Poor
	Beaver Brook	Park Ave. Carwash	Worcester						Not Enough Data
9	Middle River	St. John's Cemetery	Worcester						
10	Ararat Brook	Ford Brook	Worcester						Categories
11	Delaney Brook	Delaney Brook	Worcester						(Each category is
	Broad Meadow Brool	Dunkirk	Worcester						derived from the
13	Broad Meadow Broo	Dupuis	Worcester						combination of the
	Broad Meadow Broo		Worcester						following factors)
	Broad Meadow Broo	Knollwood	Millbury						
16	Broad Meadow Broo		Millbury						Aesthetics -
	Cold Spring Brook ^{~cw}		Sutton						turbidity, water
18	Quinsigamond River	Flint Pond Outlet	Grafton						appearance, water
19	Quinsigamond River		Grafton						odor & visual
	Quinsigamond River		Grafton						assesments
21	Quinsigamond River		Grafton						Temp temperature
22		Plantation Street	Worcester						DO - dissolved
23	Poor Farm Brook cm	Roberto Clemente	Worcester						% Sat dissolved
24	Sewall Brook	School Street	Boylston						oxygen % saturation
25	Sewall Brook ^{~cwr}	Holden Street	Shrewsbury						Nutrients - nitrate &
26	Tilly Brook	Vinny Testa's	Shrewsbury						orthophosphate
	Bummitt Brook	Pratts Pond	Grafton						
28	Singletary Brook	Sycamore Circle	Millbury						

BLACKSTONE R	KEY TO COLOR						
29/1a Blazokstone River	Fisherville Pond Outlet/12 Grafton					CODES	
*cwf = designated cold water fishery							
** = site experienced mo							

Funding provided by Blackstone Heritage Corridor, Inc.

Blackstone River Coalition Watershed-wide Volunteer Water Quality Monitoring Program Report Card for 2015 Monitoring Season

map #	WaterBody	Site Location	Town	Aesthetics	Temp.	DO	% Sat.	Nutrient s	
	Blackstone River	Sutton St. USGS flow stati	Ŭ						
	Blackstone River		Northbridge						Excellent
	Blackstone River	Tow path / Stanley Wooler							Good
33	Blackstone River	Upstream @Gorge/ Staple	Blackstone						Fair
	Blackstone River	Main St. Blackstone/TKO							Poor
	Blackstone River	River Island Park	Woonsocket						Not Enough Data
	Blackstone River **	Below Albion Dam	Lincoln						
37	Blackstone River	Slater Mill	Pawtucket						Categories
	TRIBUTARIES								(Each category is
	Mumford River	Hotel Pond Outlet	Sutton						derived from the
	Mumford River	L. Manchaug Inlet	Sutton						combination of the
	Mumford River	L. Manchaug Out./Parker I							following factors)
	Mumford River	Gilboa Street/above WWT							c ,
	Mumford River	Lackey Dam	Uxbridge						Aesthetics -
_	Mumford River	Northbridge Middle Schoo							turbidity, water
	Mumford River	Downstream @Depot Stre	0						appearance, water
	unnamed tributary	Whitin Reservoir Outlet	Douglas						odor & visual
		West Street	Douglas						assesments
47	Cook Allen Brook ^{*cwr}	Upstream of bridge/Johnso	Sutton						Temp temperature
48	West River ^{~cwr}	Hartford Avenue	Upton						DO - dissolved
49	West River ^{*cwr}	Pleasant and Glen	Upton						% Sat dissolved
50	West River ^{~cwr}	Mendon Road	Northbridge						oxygen % saturation
51	West River ^{~cwr}	Under Rte. 16 bridge	Uxbridge						Nutrients - nitrate &
	Miscoe Brook ^{*cwr}	Merriam Road	Grafton						orthophosphate
	Warren Brook ^{~cwr}	Fowler Road Bridge	Upton						
	Center Brook ^{~cwr}	Mendon Road	Upton						
	Meadow Brook ^{*cwr}	Upstream@Blackstone St.	Uxbridge						
	Emerson Brook ^{*cwr}	Above Quaker Highway	Uxbridge						
57	Bacon Brook ^{*cwr}	Balm of Life Springs Road	Uxbridge						

	TRIBUTARIES continued								
58	Mill River	Fitzgerald Street	Hopedale						CODES
59	Mill River	Mill Street	Hopedale						
60 /1a	Milzhiger	Hartford Avenue East	Hopedale						Excellent

*cwf = designated cold water fishery ** = site experienced more than 2 missed sampling events

Funding provided by Blackstone Heritage Corridor, Inc.

Blackstone River Coalition
Watershed-wide Volunteer Water Quality Monitoring Program
Report Card for 2015 Monitoring Season

map								Nutrient	
#	WaterBody	Site Location	Town	Aesthetics	Temp.	DO	% Sat.	S	
61	Mill River	Park Street Valati Park	Blackstone						Good
62	Mill River	Privilege Street	Woonsocket						Fair
	Clear River ^{con}	RI 102	Burrillville						Poor
64	Chepachet River ^{-cwr}	Gazza Road	Burrillville						Not Enough Data
65	Tarkiln Brook	Tarkiln Road	Burrillville						
66	Branch River	Rte. 146A/Great Road	N. Smithfield						Categories
67	Cherry Brook	Olo Street	Woonsocket						(Each category is
68	Crookfall Brook cm	Sayles Hill Road	Lincoln						derived from the
	Mussey Brook	New River Road	Lincoln						combination of the
70	Sneech Brook ^{corr}	Albion Road	Cumberland						following factors)
71	Monastery Brook	Mendon Road	Cumberland						Aesthetics -
72	Peters River*cwr	Paine Street	Bellingham						turbidity, water
73	Sylvys Brook	Grants Mill Road	Cumberland						appearance, water
74	Robin Hollow Pond	Dexter Street	Cumberland						odor & visual
75	Millers River ^{~cwr}	Hines Road	Cumberland						assesments
			-						Temp temperature DO - dissolved % Sat dissolved oxygen % saturation Nutrients - nitrate &

March 2016

*cwf = designated cold water fishery ** = site experienced more than 2 missed sampling events

Funding provided by Blackstone Heritage Corridor, Inc. 🔇

orthophosphate